

JOB NO. 4300 Louisiana Land & Explo-  
Loading/unloading 6/94

HER 04601

Invoices go to Houston  
H. H. + E.  
Suite 1200  
Brookhollow #2  
2950 N. Loop West  
H. Text 77092  
Accts Payable  
Ovis On rent to

---

713-957-6496  
Balva

# HERCULES

MARINE SERVICES CORPORATION

P. O. Drawer O • Freeport, Texas 77541

INVOICE NO. : 2567-94

DATE : July 14, 1994

Job No. : 4300-1

Location : Freeport Yard

TO: Louisiana Land & Exploration  
P. O. Box 88020  
Lafayette, La. 70598-9963

PLEASE REMIT PAYMENTS TO:  
11011 RICHMOND  
SUITE 500  
HOUSTON, TX. 77042

Terms : Net 30

FOR: Services as follows:

Unload barrel from truck to dock.

Labor: Journey 1 @ 31.00

Equip: Cherrypicker 1 @ 50.00

TOTAL AMOUNT DUE:

\$ 31.00

50.00

\$ 81.00

Arrived: 6/15/94

Completed: 6/15/94

PHONE: (409) 233-6371

HER 04603

Strength through Experience, Equipment, Know-How

22.8

Unload barrel &  
aim to lock.

### **TOTAL HOURS**

APPROVED  
BY

**HER 04604**

№ 13334

**- SALES ORDER -**

**Date Issued**

**B/L #** \_\_\_\_\_

Del. by: \_\_\_\_\_

Requested Delivery Date:

PO# 1AF 28965 REG # 61313-0210

Salesman # 3022

Terr. 04Dist. 01Whse. 40

State delivering to:

Parish

**Bid**

**Customer Name**

**Ordered By**

**Customer #**

### Comments

\* Deliver to Hercules Dock @ SurfSide  
Label drum w/ CO. name & Platform  
Take MADS & Get Signature (Directions & # Attached)

[illegible]

— FOR OFFICE USE ONLY —

**Are the above leases or wells to be invoiced:**

**Together** \_\_\_\_\_

**Separately** \_\_\_\_\_

**INVOICE #**

HER 04605

Job #: 4300	Invoice #:
Date Started: June 15, 1994	Date Finished: June 15, 1994
Job Type: LOADING UNLOADING	
Customer: LOUISIANA LAND & OIL	Barge Name/#: LOADING

WASTE WATER DISPOSAL			
# of Gallons:	x \$ 0.35	per gallon =	\$: 0.00

[illegible]

Invoice #	Vendor	P.O. #	Amount
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	:
:	:	:	: <b>HER 04606</b>
:	:	:	:

**HER 04606**

INITIAL MATERIALS:-----2.00

## 1. AFOF HOURS

[illegible]

LABOR HOURS con't

[illegible]

**HER 04607**

# MATERIAL SAFETY DATA SHEET

CLEARTRON HZB-44

## SECTION 1 - IDENTIFICATION

IBM 85445

Champion Technologies, Inc.  
3130 FM 521 Fresno, TX 77545  
PO. BOX 450499 Houston, TX 77545

EMERGENCY TELEPHONE NUMBERS  
1-713-431-2561  
1-800-424-9300 CHEMTREC

Trade Name: CLEARTRON HZB-44

Chemical Family: Alkylpyridine/Styrene Co-Polymer

CAS No.: PROPRIETARY

Prepared: 6/09/93

Prepared by: J. Schornick

## SECTION 2 - HAZARDOUS INGREDIENTS/IDENTITY

Hazardous Components	CAS No.	Wt. %	OSHA (PEL)
# METHANOL	67-56-1	18	200ppm
ALKYL PYRIDINE	MIXTURE	ND	NE

# Denotes SARA Title III Hazardous Ingredient.

SARA Title III Hazard Categories:

1, 3

## SECTION 3 - PHYSICAL & CHEMICAL CHARACTERISTICS

Boiling Point, F:	ND	Specific Gravity (H2O=1):	0.975
Vapor Pressure (mm Hg):	ND	Evaporation Rate:	ND
Vapor Density (Air=1):	ND	(butyl acetate=1)	
pH:	0.8-1	Viscosity:	90-120 cps
Solubility in Water:	SOLUBLE		
Appearance and Odor:	WATER WHITE AMBER LIQUID WITH DISTINCTIVE ODOR		

## SECTION 4 - FIRE & EXPLOSION DATA

Flash Point, F & Method	Flammable Limits:	LEL, % 6	UEL, % 36.5
60 PMCC	Based on: METHANOL		

### FIRE HAZARDS:

Flammable/Combustible material may be ignited by heat, sparks or flames. Vapors may travel to a source of ignition and flash back. Containers may explode in heat or fire. Vapor explosion hazard indoors, outdoors or in sewers. Runoff may create fire or explosion hazard.

### EXTINGUISHING MEDIA:

Dry chemical, CO2, water spray or regular foam. Move container from fire area if you can do it without risk. Apply cooling water to sides of containers that are exposed to flames until well after the fire is out. DO NOT get water inside container. Stay away from ends of containers.

Abbreviations: NA=not applicable, ND=not determined, NE=not established

HER 04608



## CLEARTRON HZB-44

-----  
SECTION 5 - PHYSICAL HAZARDS (REACTIVITY DATA)  
-----

Chemical Stability: STABLE

Conditions To Avoid: OPEN FLAMES, SPARKS

Incompatibility (materials to avoid): STRONG OXIDIZERS, BASES

Hazardous Decomposition/Byproducts: OXIDES OF CARBON AND NITROGEN

Hazardous Polymerization: WILL NOT OCCUR

Hazard Rating Scale: HEALTH: 2 FIRE: 3 REACTIVITY: 0

(4=severe, 3=serious, 2=moderate, 1=slight, 0=minimal)  
-----SECTION 6 - HEALTH HAZARDS  
-----

## PRIMARY ROUTES OF ENTRY

Inhalation: X Absorption: X Ingestion: X Injection: NA

## HEALTH HAZARDS:

May be hazardous if inhaled, ingested or absorbed through the skin. Direct contact with eyes and skin may cause severe damage and burns. Vapors or mists may cause irritation of mucous membranes. Ingestion and inhalation may cause headaches, nausea, dizziness and other symptoms of central nervous system depression. Repeated or prolonged exposure may cause such effects as excessive fatigue, reduced memory, and numbness.

## EMERGENCY &amp; FIRST AID PROCEDURES:

In case of EYE contact, immediately flush with running water for at least 15 minutes. In case of SKIN contact, wash with soap and water. In case of INGESTION, call a physician and dilute with water or induce vomiting as directed. In case of INHALATION, remove to fresh air. If not breathing, give artificial respiration. Remove all contaminated clothing and launder before rewearing.

IF CONDITIONS PERSIST, SEEK MEDICAL ATTENTION.

Carcinogenicity? NO NTP? ND IARC Monograph? ND OSHA Regulated? NO

## CLEARTRON HZB-44

-----  
SECTION 7 - SPECIAL PRECAUTIONS AND SPILL/LEAK PROCEDURES  
-----

## STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED:

Shut off ignition sources. No flares, smoking or flames in hazard area.  
Do not touch or walk through spilled material. Stop leak if you can do it  
without risk. Use water spray to reduce vapors. Take up with sand or other  
noncombustible absorbent material and place in containers for later  
disposal.

## WASTE DISPOSAL METHOD:

CONTACT AN EPA OR STATE APPROVED DISPOSAL FACILITY.

-----  
SECTION 8 - SPECIAL PROTECTION INFORMATION/CONTROL MEASURES  
-----

Respiratory Protection (Specify Type): NIOSH APPROVED RESPIRATOR IF PEL IS EXCEEDED

Ventilation: Local Exhaust: RECOMMENDED General Exhaust: RECOMMENDED

Special: USE SCBA WHEN ENTERING TANKS

Protective Gloves: CHEMICALLY RESISTANT/NON-SLIP

Eye Protection: CHEMICAL SAFETY GOGGLES/SAFETY GLASSES

Other Protective Clothing or Equipment: COVERALLS, SPLASH APRONS,  
EYEWASH AND SAFETY SHOWERS

Work/Hygenic Practices: CLEAN UP SPILLS PROMPTLY, WASH CONTAMINATED CLOTHING.

-----  
SECTION 9 - SHIPPING DATA  
-----

Champion Label No. 29

Hazard Classification:	UN/NA No.:	Labels Required:	DOT ER Guide No.:
3.2	UN 2924	FLAMMABLE & CORROSIVE	29

## Proper Shipping Name/Description:

FLAMMABLE LIQUIDS, CORROSIVE, N.O.S., 3.2, UN 2924, PG II  
(METHANOL, ALKYL PYRIDINE)

RQ in lbs.	RQ in gallons	pH:	Flash Point, F:	Pkg. Group:	IMDG Pg.No.:
27,778	3,421	0.8-1	60	II	3231

-----  
This information is based on data believed by Champion Technologies, Inc.  
to be accurate, but no warranty, express or implied is made.

HER 04610

JOB WORKSCOPE/BREAKDOWN

JOB NO: 4300 CUSTOMER: LL+E BARCE: Load

FOREMAN:	S/T	@ 36.00	\$	
	O/T	@ 51.75		
LEADMAN:	S/T	@ 33.50		
	O/T	@ 48.00		
JOURNEY:	S/T	@ 31.00		<u>31.00</u>
	O/T	@ 44.25		

DISPOSAL: \_\_\_\_\_ gal @ .35

MATERIAL: \_\_\_\_\_ plus 15%

STOCK MATERIAL: \_\_\_\_\_ PLUS 15%

EQUIP:

COMPRESSOR	@ 44.00	
AIR MOVERS	@ 5.00	
FORKLIFT	@ 20.00	
TUGBOAT	@ 80.00	
STEAM RIG	@ 60.00	
VACUUM	@ 18.00	
HAND HOSE	@ 10.00	
WELDING MACHINE	@ 15.00	
CHERRY PICKER	@ 50.00	<u>50.00</u>
CRANE	@ 130.00	
FLATBED TRUCK	@ 20.00	
3" GAS PUMP	@ 14.00	
2" STRIPPING PUMP	@ 12.00	
BUTTERWORTH	@ 10.00	
4" ELECT PUMP	@ 15.00	
WORK BARCE	@ 35.00	
CUTTING RIG	@ 8.00	
HAUL OUT	@ 1100.00	

ARRIVED: 6/15 COMPLETED: 6/15 DEPARTED: \_\_\_\_\_

PRODUCT: \_\_\_\_\_ LOAD: \_\_\_\_\_

TOTAL INVOICE : 81.00

# HERCULES OFFSHORE CO.

## MARINE REPAIR

MARINE OPERATIONS FACILITY

INVOICE NO. \_\_\_\_\_

ORDER No. 4300

CUSTOMER P.O. \_\_\_\_\_

DATE	ORDER WRITTEN	BY	CUSTOMER	NAME
	ARRIVAL			BILLING ADDRESS
	COMPLETION DATE			CITY AND STATE
	DEPARTURE DATE			PHONE NUMBER
M/V <input type="checkbox"/> BARGE <input type="checkbox"/>			WORK AUTHORIZED BY	
NAME			CITY AUTHORIZED BY	
LOA			STOCK MATERIAL <input type="checkbox"/> YES <input type="checkbox"/> NO	
WIDTH			IF YES, COMPLETE STOCK MATERIAL TRANSFER TICKET	
FOREMAN			OUTSIDE SERVICES <input type="checkbox"/> YES <input type="checkbox"/> NO	
LAST PRODUCT			IF YES, LIST	
GAS FREEING YES <input type="checkbox"/> NO <input type="checkbox"/>				
CERTIFICATE REQUIRED YES <input type="checkbox"/> NO <input type="checkbox"/>				
HAUL OUT FOR INSPECTION AND REPAIR YES <input type="checkbox"/> NO <input type="checkbox"/>				
ON WAYS DATE: _____				
ON WAYS DATE: _____				

### ITEM NUMBERS

- 1 LOADING AND UNLOADING SUPPLIES
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10

THIS SHALL SERVE AS YOUR AUTHORIZATION TO PROCEED WITH THE ABOVE.

Signed: \_\_\_\_\_ Date: \_\_\_\_\_

HER 04612

# HERCULES OFFSHORE CO.

## MARINE REPAIR

MARINE OPERATIONS FACILITY

INVOICE NO. \_\_\_\_\_

ORDER No. 4300

CUSTOMER P.O. \_\_\_\_\_

DATE	ORDER WRITTEN	6-15-94	STA
	ARRIVAL	6-15-94	
	COMPLETION DATE		
	DEPARTURE DATE		
M/V <input type="checkbox"/> BARGE <input type="checkbox"/>			
NAME		LOA	
LOA		WIDTH	
FOREMAN			
ALL			
LAST PRODUCT			
GAS FREEING		YES <input type="checkbox"/>	CERTIFICATE REQUIRED
NO <input type="checkbox"/>			YES <input type="checkbox"/>
			NO <input type="checkbox"/>
HAUL OUT FOR INSPECTION AND REPAIR		YES <input type="checkbox"/>	NO <input type="checkbox"/>
ON WAYS		DATE: _____	
ON WAYS		DATE: _____	

CUSTOMER	NAME	L L AND E	
	BILLING ADDRESS		
	CITY AND STATE		
	PHONE NUMBER		
WORK AUTHORIZED BY		O/Y AUTHORIZED BY	
STOCK MATERIAL		<input type="checkbox"/> YES	<input type="checkbox"/> NO
IF YES, COMPLETE STOCK MATERIAL TRANSFER TICKET			
OUTSIDE SERVICES		<input type="checkbox"/> YES	<input type="checkbox"/> NO
IF YES, LIST			

### ITEM NUMBERS

1	LOADING AND UNLOADING SUPPLIES
2	
3	
4	
5	
6	
7	
8	
9	
10	

THIS SHALL SERVE AS YOUR AUTHORIZATION TO PROCEED WITH THE ABOVE.

Signed: \_\_\_\_\_ Date: \_\_\_\_\_

HER 04613